



Important!

Battery Care

Thank you for choosing a MIPRO Portable PA System.

Please note that this system incorporates installed rechargeable batteries that must be charged before you first use the system. To charge, simply plug the system into a power point and let it charge for at least 8 hours.

The system should be charged on a regular basis and the batteries should never be allowed to run totally flat. Best practice if only using the system for short events is to use it on few occasions before recharging the batteries. So whilst the system shouldn't be run flat, best battery life is achieved by letting the system run for a number of hours before recharging. It is also recommended to switch the power to the unit off after recharging the batteries. For maximum battery life, do not leave the PA system plugged into power when it is not in use, or after the batteries have been fully charged.

If the unit is to be stored for an extended period, please ensure the system is charged (for at least 8 hours) at least once every 3 months.

With regular and correct use of the integrated charging system, you should expect years of trouble-free service. With incorrect use, or storing the unit without switching the unit off, the batteries can be damaged in a very short period of time.

The batteries are covered by a 3-month warranty. Batteries that are damaged due to being run flat are not covered by warranty.